

The Cliff

CARBON & CERAMIC


STYLISH
SANITARYWARE



FUTURISTIC DESIGN FOR YOU

₹

EX - WORKS PRICE LIST





FUTURISTIC DESIGN FOR YOU


IN WIDE VARIETIES OF
COLOURS AND DESIGNS
THAT MATCH YOUR MOODS
AND INTERNATIONAL
STANDARDS AS WELL

URINALS


HOLLOW	
	Urinal - 901
	Size: 325x420x615mm
SET	

HALF STALL	
	Urinal - 902
	Size: 385x400x620mm
SET	

CORINA	
	Urinal - 904
	Size: 320x345x450mm
SET	


SLEEK FLAT BACK	
	Urinal - 902
	Size: 260x320x440mm
SET	


FLAT BACK	
	Urinal - 906
	Size: 260x320x440mm
SET	

LEVIS	
	Urinal - 907
	Size: 690x285x350mm
SET	

Remark: › Urinals are only available in Grass Packing.


SQUATTING PANS

23" ORISSA	
	Squatting Pan - 1001
	Size: 580x440x300mm
SET	

20" ORISSA	
	Squatting Pan - 1002
	Size: 325x420x615mm
SET	

20" KHAZZAFF	
	Squatting Pan - 1003
	Size: 500x420x150mm
SET	

20" AQUA	
	Squatting Pan - 1010
	Size: 510x420x230mm
SET	

P TRAP	
	"P" 4 Pce - 1102
SET	

COLOUR *Spectrum*

Running



Snow White



Soft Ivory



Pink



Blue



Green



Baby Rose



Gray

Note: › Running Colour Prices are 20% Higher Than Snow White & Soft Ivory

Note: Colours printed above may differ from original colour of ceramics. For true selection, refer to actual samples or shade board.

TROUBLE SHOOTING GUIDE

ITEM	PROBLEM	PROBABLE REASONS	CORRECTIVE ACTIONS
One piece closet	1. Water not coming in bowl area while flushing	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
		There is no water in flush tank	Increase the ball cock height to the max level
	2. Water is continuously leaking inside the bowl	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
	3. Water quantity insufficient for effective flushing	Ball cock height adjusted at lower level	Increase the ball cock height to the max level
	4. Uneven flow of water from both side of closet	Closet is not levelled properly	Closet should be in proper level
Wallhung water closet	1. Water not coming in bowl area while flushing	Flush valve may not be working properly / concealed cistern is not working properly	Should change flush valve / concealed cistern
		Flush pipe is not inserted up the end of inlet hole	Insert the flush pipe up to the end of inlet
	2. Water is continuously leaking inside the bowl	Closet is not levelled properly	Closet should be in proper level
	3. Water quantity insufficient for effective flushing	Connection between closet outlet and drainage pipe is not proper	Proper connection should be made by experienced plumber
Wash basins / Table top	1. Overflow chocked and foul bad odour	Waste coupling used may be full threaded	Waste coupling should be replaced by slot cut coupling
	2. Water deposit on tap platform area and inside bowl area	Basin is not fixed in level or bracket is not in level	Should be done by proper levelling
	3. There is no tap hole in basin	Tap hole can be semi punched from back side	Tap hole should be created by plumber from semipunched area
Ewc / Pan / Anglo indian	1. Water not coming in bowl area while flushing	Flush bend is not inserted up to the end of inlet hole	Insert the flush pipe up to the end of inlet (for pan closet: check whether flush pipe is not covering flush hole which is in both side of inlet wall
		Closet / pan may not be levelled	Should be done by proper levelling

The Cliff

CARBON & CERAMIC

The Cliff
CARBON & CERAMIC

The Cliff International

+91 79778 10265

info@thecliffint.com

www.thecliffint.com