


STYLISH SAN I IARYWAR E





EX-WORKS PRICELIST



FUTURISTIC DESIGN FOR YOU

IN WIDE VARIETIES OF COLOURS AND DESIGNS THAT MATCH YOUR MOODS AND INTERNATIONAL STANDARDS AS WELL



ONE PIECE BASINS













WASH BASINS WITH FULL PEDESTAL































WASH BASINS WITH HALF PEDESTAL



















PLATFORM BASINS





Remark: > Platform Basins are only available in Grass Packing.



OVAL-B	
	Platform Basin - 304 B
	Size: 900x500x225mm
/ All	
600	
	/
	/




WALL HUNG BASINS





OLINA	
(a	Wall Hung Basin - 431
9	Size: 500x395x130mm
0	
	SET

REEMA	
	Wall Hung Basin - 436
	Size: 450x345x120mm
	SET






LARA	
	Wall Hung Basin - 435
	Size: 355x280x120mm
	SET

SPARROW	
	Wall Hung Basin - 402
	Size: 500x420x180mm
0	
	SET

SALVIA		
	Wall Hung Basin - 422	
	Size: 500x400x140mm	_
	SET	_





CALYPSO	
	Wall Hung Basin - 413
	Size: 450x305x100mm
	SET

SHAPPER		
	Wall Hung Basin - 406	
	Size: 500x300x190mm	
	SET	



CORNER		
1	Wall Hung Basin - 414	
4	Size: 400x400x200mm	
	SET	


KONA	
	Wall Hung Basin - 417
	Size: 350x350x150mm
	SET

TUNGA	
	Wall Hung Basin - 409
	Size: 450x320x200mm
(
0	
	SET






TABLE TOP BASINS



















KONG	
	Table Top Basin - 524
	Size: 550x380x170mm
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	






	Table Top Basin - 547
1	Size: 410x400x120mm







ULTRA THINNEST TABLE TOP BASINS






















MANNAZ	
	Table Top Basin - 563
N.	Size: 410x410x110mm
2	
0	
	SF






















DECORATIVE BASINS















TOP COUNTER BASINS























RECTO	
	Top Counter Basin - 615 Size: 480x370x105mm
	3126. 40083708103111111

11



UNDER COUNTER BASINS





SET

SET

Under Counter Basin - 705 Size: 460x320x180mm

MIRA





Note: > Running Colour Prices are 20% Higher Than Snow White & Soft Ivory

Note: Colours printed above may differ from original colour of ceramics. For true selection, refer to actual samples or shade board.

TROUBLE SHOOTING GUIDE

IIEW	PROBLEM	PROBABLE REASONS	CORRECTIVE ACTIONS
One piece closet	Water not coming in bowl area while flushing	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
		There is no water in flush tank	Increase the ba Il cock height to the max level
	2. Water is continuously leaking inside the bowl	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
	3. Water quantity insufficient for effective flushing	Ba Il cock height adjusted at lower level	Increase the ba Il cock height to the max level
	4. Uneven flow of water from both side of closet	Closet is not levelled properly	Closet should be in proper level
Wallhung water closet	Water not coming in bowl area while flushing	Flush valve may not be working properly / concealed cistern is not working properly	Should change flush valve / concealed cistern
		Fush pipe is not inserted up the end of inlet hole	Insert the flush pipe up to the end of inlet
	2. Water is continuously leaking inside the bowl	Closet is not levelled properly	Closet should be in proper level
	3. Water quantity insufficient for effective flushing	Connection between closet outlet and drainage pipe is not proper	Proper connection should be made by experienced plumber
Wash basins / Table top	Overflow chocked and foul bad odour	Waste coupling used may be full threaded	Waste coupling should be replaced by slot cut coupling
	Water deposit on tap platform area and inside bowl area	Basin is not fixed in level or bracket is not in level	Should be done by proper levelling
	3. There is no tap hole in basin	Tap hole can be semi punched from back side	Tap hole should be created by plumber from semipunched area
Ewc / Pan / Anglo indian	Water not coming in bowl area while flushing	Flush bend is not inserted up to the end of inlet hole	Insert the flush pipe up to the end of inlet (for pan closet: check whether flush pipe is not covering flush hole which is in both side of inlet wall
		Closet / pan may not be levelled	Should be done by proper levelling



The Cliff International
+91 79778 10265
info@thecliffint.com
www.thecliffint.com