


S T Y L I S H S A N I T A R Y W A R E





EX-WORKS PRICE LIST



FUTURISTIC DESIGN FOR YOU

IN WIDE VARIETIES OF COLOURS AND DESIGNS THAT MATCH YOUR MOODS AND INTERNATIONAL STANDARDS AS WELL




ONE PIECE CLOSETS















DAISY	
	One Piece EWC - 134
	Soft Close Seat Cover
	Mechanism
	Size: 690x370x735mm
	"S" Trap - 250, 300mm


Remarks: Any Scheme and Discount are Applicable only on ceramicware.
















) UF Seat Cover prices are Double of PP Seat Cover.



WALL HUNG CLOSETS


































WALL HUNG CLOSETS











ONE PIECE BASINS











WASH BASINS WITH FULL PEDESTAL
































WASH BASINS WITH HALF PEDESTAL


















PLATFORM BASINS





Remark: > Platform Basins are only available in Grass Packing.



OVAL-B	
	Platform Basin - 304 B
	Size: 900x500x225mm
1	
6.3	
0	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	



WALL HUNG BASINS

















SALVIA		
	Wall Hung Basin - 422	
	Size: 500x400x140mm	_
	SET	_































TABLE TOP BASINS



































ULTRA THINNEST TABLE TOP BASINS













































DECORATIVE BASINS














TOP COUNTER BASINS



























UNDER COUNTER BASINS














CLOSETS












URINALS








Remark:) Urinals are only available in Grass Packing.







SQUATTING PANS













Snow White Pink Blue Green Soft Ivory Baby Rose Gray

Note: > Running Colour Prices are 20% Higher Than Snow White & Soft Ivory

Running

Note: Colours printed above may differ from original colour of ceramics. For true selection, refer to actual samples or shade board.

TROUBLE SHOOTING GUIDE

ITEM	PROBLEM	PROBABLE REASONS	CORRECTIVE ACTIONS
	Water not coming in bowl area while flushing	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
		There is no water in flush tank	Increase the ball cock height to the max level
One piece closet	2. Water is continuously leaking inside the bowl	Mechanism inside tank may not be working properly	Change the centre pump of mechanism
	3. Water quantity insufficient for effective flushing	Ball cock height adjusted at lower level	Increase the ball cock height to the max level
	4. Uneven flow of water from both side of closet	Closet is not levelled properly	Closet should be in proper level
Wallhung water closet	Water not coming in bowl area while flushing	Flush valve may not be working properly / concealed cistern is not working properly	Should change flush valve / concealed cistern
		Fush pipe is not inserted up the end of inlet hole	Insert the flush pipe up to the end of inlet
	2. Water is continuously leaking inside the bowl	Closet is not levelled properly	Closet should be in proper level
	3. Water quantity insufficient for effective flushing	Connection between closet outlet and drainage pipe is not proper	Proper connection should be made by experienced plumber
Wash basins / Table top	Overflow chocked and foul bad odour	Waste coupling used may be full threaded	Waste coupling should be replaced by slot cut coupling
	Water deposit on tap platform area and inside bowl area	Basin is not fixed in level or bracket is not in level	Should be done by proper levelling
	3. There is no tap hole in basin	Tap hole can be semi punched from back side	Tap hole should be created by plumber from semipunched area
Ewc / Pan / Anglo indian	Water not coming in bowl area while flushing	Flush bend is not inserted up to the end of inlet hole	Insert the flush pipe up to the end of inlet (for pan closet: check whether flush pipe is not covering flush hole which is in both side of inlet wall
		Closet / pan may not be levelled	Should be done by proper levelling

